


# CORNER RECORD

# COUNTY OF PLACER, CALIFORNIA

Unincorporated

Document Number 20170001

Brief Legal Description: Parcel A — 30 PM 33 O.R.P.C.



S 9  
T 11  
R 7

## CORNER TYPE

Government Corner ☐ Control ☐  
Meander ☐ Property ☒  
Rancho ☐ Other ☐  
Date of Survey: 12-20-2016

## COORDINATES (Optional)

N.  
E.  
Zone Datum  
Elev.

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish corner:

Found the Northeast and Southeast monuments of record for Parcel 'A'. Replaced monument at the angle point in the North line in record position. Did not replace the other one because it fell in a horse corral.

A description of the physical condition of the monument as found and as set or reset:

set 3/4" rebar with plastic cap stamped LS8891

## SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction

in conformance with the Professional Land Surveyor's Act

on January 3rd, 2017.

Signed Juanita Mathis LS 8891

Expiration Date: 12-31-17



## COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 2017

and examined and filed August 29, 2017 2017


Signed Leslie Amberry PLS NO. 6584 Title County Surveyor



County Surveyor's Comment \_\_\_\_\_

## NOTE

ALL BEARINGS AND DISTANCES SHOWN HEREON  
ARE RECORD PER 30 PM 33 AND MEASURED EXCEPT AS NOTED OTHERWISE.



**CORNER RECORD**  
A PORTION OF  
SECTION 24, T.11 N., R.7 E., M.D.M.  
PLACER COUNTY, CALIFORNIA  
SCALE: 1"=60' AUGUST, 2017  
**MATHIS LAND SURVEYING**  
**COOL CALIFORNIA**  
**916-768-8984**

## LEGEND

- SET 3/4" CAPPED REBAR STAMPED LS 8891
- FND 3/4" REBAR WITH PLASTIC CAP RCE 29265



HORSE BARN

x — x — FENCE

- DIMENSION POINT SEARCHED FOR, NOTHING FOUND, NOTHING SET
- () RECORD PER 30 PM 33, ORPC

\\MATHIS-PC\Root\00Projects\044-051-091\Out\170816\044-051-071CR.dwg, 08/16/17 12:43:39pm, AutoCAD